



**D.M. STANDEN LTD**  
THE ROPE CENTRE - SLINGMAKERS CENTRE

[www.ropecentre.co.nz](http://www.ropecentre.co.nz)

Postal: P.O. Box 4360, Shortland Street, Auckland  
Physical: 73 The Concourse, Henderson, Auckland  
Phone: +64 9 837 7100 Fax: +64 9 837 7101



## CERTIFICATE OF INSPECTION

Page: 1 of 1

Customer: ARTEMIS RACING

Address: , , ,

Location: ROCNA ANCHORS

Serial No: DMS1007

Inspected By:

Stephen Pocock

Divison:

Phone: 021 804199

Reference #:

Order #: SO29725

P.O. #:

Equipment Type: Anchor Inspection

Inspection Result: N/A

Inspected On: 11/05/2011 1:26 PM NZST

D.M. Standen Ltd's code of practice requires that a rigorous visual inspection is carried out prior to proof loading, and that all equipment is tested according to relevant National or International safety standards. Where no such standard exists, the manufacturers requirements are followed. If the testing requirements of a standard are different to those required by the New Zealand Rigging code of Practice, then the requirements of the code are used.

### Inspection Comments:

#### Anchor Inspection

Manufacturer: ROCNA ANCHORS  
Type: Galvanised Rocna Original, Model: 55  
Weight Of Anchor: 55 kg-121 lbs  
Proof Load: 4,386 kg

#### Item Comments:

After Proof Loading Anchor Also Taken To The Specified Minimum Breaking Load Of 12mm Chain 16,693 kg, Held Test Load Successfully. Anchor Then Taken To Destruction, Shank On Anchor Failed & Twisted @ 28,720 kg.

NOTE: Did Not Break!

Anchor	Status	Comments
Shank	Pass	
Fluke	Pass	
Pins	N/A	
Connectors	N/A	
Shackle	Pass	
Other (Please note)	N/A	
Proof Load	Pass	-Held Test Loads Successfully.

### Supporting Images